



PIN OUT

PIN 1 — FUSE RED STRIP&TIN

PIN 2 — BLACK STRIP&TIN

TESTING CONDITION:
 COND: 2 Ohm
 I.R: 20M Ohm
 HI-POT:DC 200V/0.5S