





MARKING "J"




LABEL1



LABEL2




SECTION VIEW A-A



PIN OUT

PIN 1 — FUSE RED STRIP&TIN

PIN 2 — BLACK STRIP&TIN



TESTING CONDITION:  
 COND: 2 Ohm  
 I.R: 20M Ohm  
 HI-POT:DC 200V/0.5S