



TESTING CONDITION
 A.CONDUCTIVE RESISTANCE 2 Ohm Max.
 B.INSULATION RESISTANCE 20M Ohm Min
 WITH DC200V DURING 0.5second.

WIRE LIST

(J3)	P7	20AWG	GRAY/BLACK	(J1)	P9
	P5	20AWG	GRAY		P10
	P6	20AWG	WHITE/BLACK		P11
	P8	20AWG	WHITE		P12
	P1	20AWG	GREEN		P8
	P2	20AWG	GREEN/BLACK		P7
	P3	20AWG	PURPLE/BLACK		P6
(J4)	P4	20AWG	PURPLE		P5
	P1	20AWG	RED		P2
	P2	20AWG	BLUE		P4
	P3	20AWG	ORANGE	(J5)	P1
(J2)	P4	20AWG	BROWN		P2
	P1	16AWG	YELLOW	FUSE	P1
	P2	16AWG	BLACK		P3